

WORKOVER PROCEDURE

WELL NAME: STATE A36-03 **DATE:** 3/11/2015

LOCATION: Qtr/Qtr: NE/NE Section: 36 Township: 6N Range: 64W

Footages: 683' FNL & 2028' FWL

COUNTY: WELD **STATE:** CO **API #:** 05-123-14743

ENGINEER: Jonathan Pomerantz 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 277' KB Elevation: 4634'
Surface Cmt: 250 sx GL Elevation: 4624'
Long St Csg: 2 7/8" 6.5# @ 6955' TD: 6955'
Long St Cmt: 275 sx PBTD: 6873'
Long St Date: 9/30/1990

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 6793' - 6804'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 1 2/3" 2.3# @ 6778' Rods: _____
Pump: _____
Misc.: **Casing Patch @ 5762' (7/21/2000)**

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 2/3" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6743', dump bail 2 sx of cement on top.
- 4) Load hole. Run CBL to confirm annular cement depths.
- 5) RIH w/ workstring to 6743'. Pump 10 sx balance plug. SI, WOC. RIH. Tag balance plug @ approx 6398'.
- 6) RIH w/ workstring to 5900'. Pump 25 sx balance plug. SI, WOC. RIH. Tag balance plug @ approx 5000'.
- 7) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 8) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 9) POOH w/ workstring to 500'. Pump 200 sx shoe plug. Cement to surface.
- 10) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 11) Cut surface casing off 6'-8' below ground.
- 12) Clean up location. Reclaim location. RDMO.