

**WORKOVER PROCEDURE**

**WELL NAME:** UPV 31-13G3 **DATE:** 3/11/2015

**LOCATION:** Qtr/Qtr: SW/SW Section: 31 Township: 6N Range: 63W

Footages: 658 FSL & 615 Township: 6N Range: 63W  
FWL

**COUNTY:** WELD **STATE:** CO **API #:** 05-123-18634

**ENGINEER:** DARYL KVEDER 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 7" 17# H-40 @ 415' KB Elevation: 4621  
Surface Cmt: 130 sx GL Elevation: 4632  
Long St Csg: 2-7/8" 6.5# N-80 TD: 6903  
Long St Cmt: 115 sx PBDT: 6822  
Long St Date: 10/17/1994

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Niobrara Perforations (6470-6480, 6560-6584, 6634-6644)  
Perforation Interval (2): Codell Perforations (6740-6760, 6747-6759)  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 1-1/2" 2.76 @ 6722' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

**PROCEDURE:**

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1-1/2" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6420', dump bail 2 sx of cement on top.
- 4) RIH w/workstring to 6420'. Pump 14 sx balance plug. SI, WOC, RIH. Tag balance plug @ 5910'.
- 5) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 465'. Pump 120 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.