

WORKOVER PROCEDURE

WELL NAME: SCHOLFIELD A36-19 **DATE:** 3/18/2015
LOCATION:
Qtr/Qtr: NW/NW Section: 36 Township: 6N Range: 64W
Footages: 1320 FNL & 1170 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-25768

ENGINEER: DARYL KVEDER 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# J-55 @ 440' KB Elevation: 4640'
Surface Cmt: 213 sx GL Elevation: 4627'
Long St Csg: 4-1/2" 11.6# M-80 @ 6950.8' TD: 6966'
Long St Cmt: 680 sx PBTD: 6893'
Long St Date: 6/22/2008

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations (6522-6538', 6632-6648')
Perforation Interval (2): Codell Perforations (6809-6821')
Perforation Interval (3): _____
Tubing: 2-3/8" 4.7# J-55 @ 6791.1' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6472', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to 2500'. pump 20 sx balance plug.
- 5) Unland casing. Cut casing off @ 1700'. POOH with casing laying down on trailer. If unable to unland csg cut while holding
- 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 470'. Pump 160 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.