

WORKOVER PROCEDURE

WELL NAME: Wirth #1-12 **DATE:** 3/12/2015
LOCATION:
Qtr/Qtr: NENE Section: 12 Township: 6N Range: 59W
COUNTY: Morgan **STATE:** CO **API #:** 05-087-07250

ENGINEER: 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: Re-Enter and Replug

WELL DATA: Surface Csg: 8 5/8" 24# @180' KB Elevation: 4853'
Surface Cmt: 125 sacks cement GL Elevation: 4846'
Long St Csg: 5.5" 14# & 15.5# @ 6582' - Pulled 4850' TD: 6582'
Long St Cmt: 250 sx, TOC @5810 PBTD: 6555'
Long St Date: _____

Plug Info (1) 35 sx @ 6440' - 5452', Through Perfs
Plug Info (2) 15 sx @ Base of Surface
Plug Info (3) 10 sx @ Surface
Plug Info (4) _____

Tubing: _____ Rods: _____
Pump: _____
Misc.: _____

WELL STATUS: P&A 8/14/1975

COMMENTS: No mention of welded cap on surface casing, or if cut below surface. Deepest waterwell depth is 331', Fox Hills is 410'.

PROCEDURE:

- 1) Survey and locate abandoned well, mark with stake.
- 2) Excavate.
- 3) Drill out surface, role hole clean. Verify and tag top of first plug.
- 4) Drill out first plug, role hole clean. Verify and tag top of next plug.
- 5) Drill out second plug, role hole clean.
- 6) Set plug @ 1500' - 1400' w/ 45 sx, set and tag.
- 7) Set surface Plug @ 430' - Surface w/ 245 sx, set and tag.
- 8) POOH RDMO, weld on cap.
- 9) Reclaim surface.