

REENTRY PROCEDURE

WELL NAME: State 6525 #11-32 DATE: 2/3/2015

LOCATION: Qtr/Qtr: NWNW Section: 32 Township: 6N Range: 63W

COUNTY: WELD STATE: CO API #: 05-123-20367

ENGINEER: Hunter Dunham 7 Day Notice Sent: _____

(Please notify Engineer of any major changes prior to work) Do not start operations until: _____

Notice Expires: _____

OBJECTIVE: Re-enter and re-plug

WELL DATA: Surface Csg: 8 5/8" 24# 399' KB Elevation: 4680'

Surface Cmt: 280sxs to surface GL Elevation: 4670'

Long St Csg: NO PROD CSG TD: 6987'

Long St Cmt: _____ PBTD: _____

Long St Date: _____

Plug Info (1) 50sxs @ 6530'

Plug Info (2) 50 sx from 350'-450'

Plug Info (3) 10 sx @ surface

Plug Info (4) _____

Tubing: _____ Rods: _____

Pump: _____

Misc.: Base Fox Hills 361', Deepest water well 600'

WELL STATUS: Well Abandoned 09/2001

COMMENTS: _____

PROCEDURE:

- 1) Survey and locate abandoned well, mark with stake
- 2) Excavate to expose top of surface casing
- 3) Weld 2" collar to top of 8 5/8" surface casing cap. Make up to collar, pneumatic drill with non-sparking bit. Drill out cap venting possible trapped gas.
- 4) Once verified that no gas exists beneath top of surface casing plate, cut off surface casing below plate with torch, dress up smooth.
- 5) Butt weld 8 5/8" casing to dressed cut, bringing threaded end of casing to ground level.
- 6) Make up to 8 5/8" casing, one 8 5/8" collar and 8 5/8" starter well head
- 7) NU flange adaptor and 5k BOP, test BOP.
- 8) NU and RIH with 6 7/8" cone bit, PU 2 7/8" drill collar, 2 7/8" 8.7# tubing, and TIW valve
- 9) Drill out first cement plug inside surface casing, roll hole clean. Verify top of next cement plug inside of surface casing by tagging (near 350').
- 10) If unable to verify isolation of surface casing with tag of cement plug, set RBP inside surface casing
- 11) Once isolation of surface casing is established, either with tagging of surface plug or setting of RBP, pressure test surface casing to 200psi
- 12) After pressure test of surface casing, retrieve RBP or continue drill out of cement plug under surface casing shoe.
- 13) Assume pressure under surface casing shoe, roll hole with kill fluid until well dead, or blow down.
- 14) Continue RIH, cleaning out with drilling mud or water to 3000'
- 15) TOOH with cone bit, drill collars, and 2 7/8" tubing.
- 16) PU and RIH with mule shoe and 2 7/8" tubing to 3000'
- 17) RU cement crew and pump 100sk 15.8 ppg Class G "neat" cement
- 18) POOH to 700' (100' below base of Fox Hills @ 600')
- 19) RU cement crew and pump 265sk 15.8 ppg Class G "neat" cement. Bring to surface
- 20) POOH with 2 7/8" tubing. Wait 4 hrs, and tag TOC. If cement has fallen, top off back to surface
- 21) Let cement set over night, verify cement has not settled and is still at surface. RDMO