

WORKOVER PROCEDURE

WELL NAME: UPV 31-16G3 DATE: 3/30/2015

LOCATION: Qtr/Qtr: SE/SE Section: 31 Township: 6N Range: 63W

Footages: 663 FSL & 645 FEL

COUNTY: WELD STATE: CO API #: 05-123-18635

ENGINEER: DARYL KVEDER 7 Day Notice Sent: (Please notify Engineer of any major changes prior to work) Do not start operations until: Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 7" 17# K-55 @ 451' KB Elevation: 4666 Surface Cmt: 210 sx GL Elevation: 4663 Long St Csg: 2-7/8" 6.5# @ 6902' TD: 6936 Long St Cmt: 105 sx PBTD: 6853 Long St Date:

Plug Back (Sand or CIBP): Perforation Interval (1): Niobrara Perforations (6512-6532, 6634-6650) Perforation Interval (2): Codell Perforations (6791-6811) Perforation Interval (3): Tubing: 1.66" 2.3# J-55 @ 6777' Rods: Pump: Misc.:

PRODUCTION STATUS: COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank. 2) POOH w/ 2 3/8" tbg and lay down. 3) RU WL. RIH w/ CIBP. Set CIBP @ 6468', dump bail 2 sx of cement on top. 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer. 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug. 6) POOH w/ workstring to 750'. Pump 175 sx shoe plug. Cement to surface. 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed. 8) Cut surface casing off 6'-8' below ground. 9) Clean up location. Reclaim location. RDMO.