

Document Number:
400785237

Date Received:
02/03/2015

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 47120 Contact Name: Cheryl Light

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP Phone: (720) 929-6461

Address: P O BOX 173779 Fax: (720) 929-7461

City: DENVER State: CO Zip: 80217- Email: cheryl.light@anadarko.com

For "Intent" 24 hour notice required, Name: Carlile, Craig Tel: (970) 629-8279

COGCC contact: Email: craig.carlile@state.co.us

API Number 05-123-15135-00

Well Name: WEBER L Well Number: 4-5

Location: QtrQtr: SWNW Section: 4 Township: 3N Range: 66W Meridian: 6

County: WELD Federal, Indian or State Lease Number: _____

Field Name: WATTENBERG Field Number: 90750

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.255450 Longitude: -104.789520

GPS Data:
Date of Measurement: 12/02/2009 PDOP Reading: 2.1 GPS Instrument Operator's Name: DAVID HOLMES

Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____

Casing to be pulled: Yes No Estimated Depth: 4540

Fish in Hole: Yes No If yes, explain details below

Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7300	7316			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	412	290	412	0	VISU
1ST	7+7/8	2+7/8	6.5	7,426	300	7,426	6,475	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7226 with 20 sacks cmt on top. CIBP #2: Depth 80 with 25 sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 20 sks cmt from 7226 ft. to 6600 ft. Plug Type: CASING Plug Tagged:
Set 390 sks cmt from 4540 ft. to 4030 ft. Plug Type: OPEN HOLE Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 420 sacks half in. half out surface casing from 1100 ft. to 200 ft. Plug Tagged:

Set 25 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

5 MIRU workover rig. ND WH, NU BOPs. Spot trailer with 30 jnts of 1.66" IJ tubing for replacement. Circulate with fresh water with biocide to control well.

6 Notify Cementers to be on call.

7 MIRU WL. RIH w/ gauge ring and junk basket for 2-7/8", 6.5#, csg to 7300'. RIH w/ CIBP for 2-7/8" tbg and set at 7226'. (Nearest collars are at 7220' and 7236'). RD WL.

8 RIH w/ 1.66" IJ tbg while hydrotesting to 3000 psi. Tag CIBP at 7226' and PU 5'. Circulate tubing with fresh water and biocide to remove all gas and PT casing to 3000 psi for 15 minutes. Notify Evans Engineering of results of PT.

9 "RU Cementers. Pump Niobrara balanced plug: 5 bbls (20 sks) "G" w/ 20% silica flour, 0.4% CD -32, 0.4% ASA -301 and R-3 to achieve 2:30 pump time mixed at 15.8 ppg and 1.38 cuft/sk. Cement to cover from 7226' to 6600' inside the 2-7/8" casing.

10 PUH while laying down to 6200' and circulate hole clean of excess cement. POOH and LD tbg on trailer.

11 MIRU WL. Cut casing at or below 4540'. RD WL.

12 Circulate down the casing taking returns up the surface casing removing all gas from wellbore. Pump ~1.5x wellbore volumes ~ 450 bbls fresh water with biocide. Plan on pumping 5 gallon sweeps of mud thinner as needed during circulation to condition wellbore for cement job. If unable to establish circulation, contact Evans Engineering.

13 ND BOP and wellhead. Install a BOP on surface casing head with 2-7/8" pipe rams. Install 3000 psi ball valves on both casing head outlets. Install a choke or choke manifold on one outlet.

14 RU Cementers. Pump Sussex Balanced plug: Preceed cement with 5 bbls water, 20 bbls Sodium Metasilicate (SMS) and another 5 bbl fresh water spacer ahead of 80 bbls (390 sks) "G" w/ 0.4% CD-32, 0.4% ASA-301, .25 pps cello flake with CaCl2 as necessary. Mixed at 15.8 ppg, 1.15 cuft/sack. Calculated top of plug is at 4030' in 11.5" openhole with 20% excess. PUH to ~3700' and circulate hole clean. WOC per cement company recommendation.

15 RIH w/ 2-7/8" csg and tag top of plug at 4030' or shallower. PUH while laying down to 1100'.

16 RU Cementers. Pump Fox Hills Balanced plug: Pump 10 bbls SAPP mud flush followed by 20 bbls fresh water spacer ahead of 99.5 bbls (420 sx) Type III w/ .25 pps cello flake and CaCl2 as deemed necessary, mixed at 1.33 cf per sack, 14.8 ppg. Plug size is based on ~9.5" offset hole with 40% excess covering 1100' to shoe of surface casing at 412' plus capacity of surface casing to 200'. PUH to 100' and circulate out any excess cmt. TOH and WOC per cement company recommendation.

17 RIH and tag top of plug. Plug needs to be tagged at 300' or higher. POOH and LD 2-7/8" csg.

18 RU WL. RIH and set CIBP in the 8 5/8", 24# surface casing at 80'. PT CIBP and surface casing to 1000 psi for 15 minutes. Assuming successful test, RD wireline. RDMO workover rig.

19 Instruct cementing and wireline contractors to e-mail copies of all job logs/job summaries to rscDJVendors@anadarko.com within 24 hrs of completion of the job.

20 Supervisor submit paper copies of all invoices, logs, and reports to Joleen Kramer.

21 Excavation crew to notify One Call to clear excavation area around wellhead and for flowlines.

22 Excavate hole around surface casing enough to allow welder to cut casing minimum 5' below ground level.

23 Welder cut casing minimum 5' below ground level.

24 Fill casing to surface using 4500 psi compressive strength cement, (NO gravel).

25 Spot weld on steel marker plate. Marker should contain Well name, Well number, legal location (1/4 1/4 descriptor) and API number.

26 Obtain GPS location data as per COGCC Rule 215 and send to rscDJVendors@anadarko.com.

27 Properly abandon flowlines per Rule 1103. File electronic Form 42 once abandonment complete.

28 Back fill hole with fill. Clean location, level.

29 Submit Form 6 to COGCC ensuring to provide 'As performed' WBD identifying operations completed.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Cheryl Light
 Title: Sr. Regulatory Analyst Date: 2/3/2015 Email: cheryl.light@anadarko.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SCHLAGENHAUF, MARK Date: 4/2/2015

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: 10/1/2015

COA Type	Description
	1) Submit Form 42 electronically to COGCC 48 hours prior to MIRU. 2) If unable to pull casing contact COGCC for plugging modifications. 3) For 1100' plug: pump plug and displace, shut-in, WOC 4 hours and tag plug – must be 362' or shallower. 4) Properly abandon flowlines as per Rule 1103. File electronic Form 42 once abandonment complete. 5) Please submit existing gyro survey data with Form 6 (s) Subsequent Report of Abandonment.

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
400785237	FORM 6 INTENT SUBMITTED
400785241	PROPOSED PLUGGING PROCEDURE
400785242	WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	Changed 20 sxs annulus plug to casing plug, added plug tagged check box to shoe plug half in and half out of surface casing, changed fish in hole from yes to no after checking w/ operator.	4/1/2015 9:56:37 AM
Permit	Well Completion Report dated 10/16/1991.	2/3/2015 10:59:42 AM

Total: 2 comment(s)