

WORKOVER PROCEDURE

WELL NAME: KOHLHOFF USX AB17-16 DATE: 4/13/2015

LOCATION: Qtr/Qtr: SESE Section: 17 Township: 7N Range: 64W

Footages: 662' FSL & 662' FEL

COUNTY: WELD STATE: CO API #: 05-123-26090

ENGINEER: Jason Lehman 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# J-55 @ 722' KB Elevation: 4,924'
Surface Cmt: 320 sxs GL Elevation: 4,912'
Long St Csg: 4-1/2" 11.6# M-80 @ 7,316' TD: 7,318'
Long St Cmt: 970 sxs PBSD: 7,300'
Long St Date: 8/13/2007

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations: 6,864' - 6,880'; 6,971' - 6,982'
Perforation Interval (2): Codell Perforations: 7,145' - 7,159'
Perforation Interval (3): _____
Tubing: 2-3/8" 4.7# J-55 @ 7,207' Rods: 6,725' x 3/4", 400 'x 1-1/4" SB
Pump: 1-1/4" RHAC
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ ^{814'}6,704', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to 2500'. Pump 50 sx balance plug. SI, WOC. RIH. Tag balance plug @ approx. 1840'.
- 5) Cut casing off @ 900'. POOH w/ csg laying down on trailer.
- 6) RIH w/ workstring to 900'. Pump 280 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.