

## WORKOVER PROCEDURE

**WELL NAME:** Huwa 11-2 **DATE:** 4/14/2015  
**LOCATION:**  
Qtr/Qtr: SW/NE Section: 11 Township: 4N Range: 65W  
Footages: 1960 FSL & 1956 FWL  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-14717

**ENGINEER:** Jocelyn Perroux 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8-5/8", 24 ppf @ 400' KB Elevation: 4,695  
Surface Cmt: 150 sx GL Elevation: 4,685  
Long St Csg: 4-1/2", 12.60 ppf, N-80 @ 7,119' TD: 7,119  
Long St Cmt: 670 sx PBTD: 7,083  
Long St Date: 9/9/1990

Plug Back (Sand or CIBP): **Sand (circ. Clean to PBTD)**  
Perforation Interval (1): Niobrara Perforations 6,710 - 6,903'  
Perforation Interval (2): Codell Perforations 7,009 - 7,024'  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2-3/8" @ 7,010' Rods: NA  
Pump: NA  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** PR  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6,660', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2,500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 520'. Pump 200 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.