

**WORKOVER PROCEDURE**

**WELL NAME:** Lamp H26-01 **DATE:** 4/14/2015

**LOCATION:** Qtr/Qtr: NE/NE Section: 26 Township: 3N Range: 65W

Footages: 1295 FNL & 180' FEL

**COUNTY:** WELD **STATE:** CO **API #:** 05-123-27395

**ENGINEER:** Benjamin Daniell 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# J-55 @ 680' KB Elevation: 4867'  
Surface Cmt: 470 sx GL Elevation: 4855'  
Long St Csg: 4 1/2" 11.6# M-80 @ 7832' TD: 7845'  
Long St Cmt: 650 sx PBTD: 7351'  
Long St Date: 11/15/2006

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Niobrara Perforations 6988'-7012'  
Perforation Interval (2): Codell Perforations 7238'-7246'  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8" 4.7# J-55 @ 7200' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** Producing

**COMMENTS:** BH Failure/ Fox Hills Exposed

**PROCEDURE:**

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6938', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 842'. Pump 330 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.