

**WORKOVER PROCEDURE**

**WELL NAME:** ODLE BB18-13 **DATE:** 4/15/2015

**LOCATION:** Qtr/Qtr: SW/SW Section: 18 Township: 5N Range: 63W

Footages: 646 FSL & 639 FWL

**COUNTY:** WELD **STATE:** CO **API #:** 05-123-15528

**ENGINEER:** DARYL KVEDER 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8-5/8" 24# @ 314' KB Elevation: 4573  
Surface Cmt: 130 sx GL Elevation: 4561  
Long St Csg: 2-7/8" 6.5# N-80 @ 6756' TD: 6756  
Long St Cmt: TOC @ 5694' sx PBTD: 6713  
Long St Date: 2/5/1992

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Codell Perforations (6601-6613')  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 1.9" 2.75# J-55 @ 6573' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

**PROCEDURE:**

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1.9" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6551', dump bail 15 sx of cement on top to ensure coverage over Nio
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 416'. Pump 140 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.