

Engineer: Heath Pottmeyer

Cell: 740-525-3445

Date: 4/16/2015

PLUG AND ABANDONMENT PROCEDURE

HSR-CANTWELL 7-16, API 05-123-16048

Steps

1. Provide 48 hour notice to COGCC prior to rig up per request on approved Form 6 (e.g. call field coordinator, submit Form 42, etc.). Call Automation Removal Group at least 24 hours prior to rig move. Request they catch and remove plunger, isolate production equipment and remove any automation prior to rig MIRU.
2. MIRU slickline services. Pull bumper spring and tag bottom. RDMO slickline services.
3. Prepare location for base beam equipped rig. Install perimeter fence as needed.
4. Check and record bradenhead pressure. If bradenhead valve is not accessible, re-plumb so that valve is above GL.
5. MIRU, kill as necessary using biocide treated water. NDWH. NUBOP. Unseat landing jt, LD.
6. Notify cementers to be on call. Provide volumes listed below:
 - 6.1 Niobrara plug: 25 sx (35 cu-ft) "G" w/ 20% silica flour, 0.4% CD-32, 0.4% ASA-301 and R-3 to achieve 2:30 pump time. Mix at 15.8 ppg and 1.38 cu-ft/sk. Cement volume based on 400' in 4 ½" casing.
 - 6.2 Sussex suicide: 240 sx (276 cu-ft) "G" w/ 0.25 pps cello flake, 0.4% CD-32, 0.4% ASA-301, mixed at 15.8 ppg and 1.15 cu-ft/sk. Cement volume based on 720' in 4 ½" casing and 520' in a 9" OH with 20% excess. Caliper on file.
 - 6.3 Foxhills plug: 160 sx (213 cu-ft) Type III w/ cello flake and CaCl₂ as necessary, mixed at 14.8 ppg and 1.33 cu-ft/sk. Cement volume based on 100' in 4 ½" casing, 248' in a 9" OH with 20% excess, and 202' in 8 5/8" casing. Caliper on file.
7. TOOH 2 3/8" and 1.66" tubing landed at 7456'. Stand back 2 3/8" tubing and lay down 1.66" tubing.
8. MIRU WL. RIH gauge ring for 2 7/8" 6.5# casing to 7450'. POOH.
9. PU 2 7/8" 6.5# CIBP and RIH w/ WL. Set at +/- 7420' to abandon J Sand perfs. PU dump bailer, dump bail 1 sx class "G" cement on CIBP. POOH.
10. RIH gauge ring for 4 ½" 11.6# casing to 6750'. POOH.
11. PU 4 ½" 11.6# CIBP and RIH w/ WL. Set at +/- 6730' to abandon Niobrara and Codell perfs. PT to 1000 psi for 15 minutes. RDMO WL.
12. RIH with 2 3/8" tubing to +/- 6730', tag CIBP and PUH 5'. Hydrotest tubing to 3000 psi while RIH.
13. RU cementers. Pump Niobrara plug: 25 sx (35 cu-ft) "G" w/ 20% silica flour, 0.4% CD-32, 0.4% ASA-301 and R-3 to achieve 2:30 pump time. Mix at 15.8 ppg and 1.38 cu-ft/sk. Plug to cover 6330' – 6730'.
14. PUH to +/- 6100'. Reverse circulate with biocide treated water to displace cement and clear tubing.
15. POOH. Stand back 3760' of tubing.

TOC – 5930'

NB Top – 6783', SX Top – 3936', FHM – 680'

Offset to Iceman State 5-15HZ, Maverick State 4-15HZ, & Merlin 13-15HZ Pads in Top Gun Campaign Pasture

Gyro Completed 11/5/2014

No Known Casing Issues

16. RU WL. PU 3 1/8" perf guns with 3 spf, 120 degree phasing, 0.50" EHD and RIH w/ WL. Shoot 1' of squeeze holes at 4250' and 2' of squeeze holes at 3730'. RD WL.
17. PU and RIH w/CICR and 2 3/8" tubing, set CICR at +/- 3760'. Establish circulation with rig pump using biocide treated water.
18. RU cementers. Establish circulation with biocide treated water and precede cement with 5 bbl water containing biocide, 20 bbl sodium metasilicate and another 5 bbl water spacer.
19. Pump Sussex suicide: 240 sx (276 cu-ft) "G" w/ 0.25 pps cello flake, 0.4% CD-32, 0.4% ASA-301, mixed at 15.8 ppg and 1.15 cu-ft/sk to place cement between perms from 4250' to 3730'. Under displace and sting out of CICR to leave 3 bbls (~200') on top of retainer. Cement volume based on 9" OH with 20% excess. Caliper readings across entire interval. RD cementers.
20. PUH to +/- 3300'. Reverse circulate with biocide treated water to displace cement and clear tubing.
21. P&SB 900', LD remainder.
22. RU WL. Shoot off 4 1/2" casing at or below 800'. RD WL. Circulate casing with biocide treated water to remove any gas.
23. NDBOP, NDTH.
24. Install BOP on casing head with 4 1/2" pipe rams.
25. TOOH 4 1/2" casing, LD.
26. RIH with 2 3/8" tubing to 900' inside 4 1/2" casing.
27. RU cementers. Establish circulation with biocide treated water and precede cement with 10 bbl SAPP and a minimum 20 bbl fresh water spacer. Pump Foxhills plug: 160 sx (213 cu-ft) Type III w/ cello flake and CaCl₂ as necessary, mixed at 14.8 ppg and 1.33 cu-ft/sk. Plug to cover 900' – 800' in 4 1/2" casing, 800' – 552' in 9" OH with 20% excess, and 552' – 350' in 8 5/8" casing. Caliper readings across entire interval. RD cementers.
28. PUH to 100' and circulate with biocide treated water to displace cement and clear tubing.
29. WOC per cement company recommendation. Tag cement at or above 450'. If not, consult with Evans Engineering.
30. RU WL. RIH 8 5/8" 24# CIBP to 80'. Set and pressure test to 1000 psi for 15 minutes. If tests, RDMO WL and WO rig.
31. Instruct cementing and wireline contractors to email copies of all job logs/jobs summaries to rscDJVendors@anadarko.com within 24 hours of completion of the job.
32. Supervisor is to submit paper copies of all invoices, logs, and reports to Evans Engineering Specialist.
33. Excavation crew to notify One Call to clear excavation area around wellhead and for flowlines.
34. Excavate hole around surface casing enough to allow welder to cut casing minimum 5' below ground level.
35. Welder cut casing minimum 5' below ground level.
36. Fill casing to surface using 4500 psi compressive strength cement, (NO gravel).
37. Spot weld on steel marker plate. Marker should contain well name, well number, legal location (1/4 1/4 descriptor) and API number.
38. Obtain GPS location data as per COGCC Rule 215 and send to rscDJVendors@anadarko.com.
39. Properly abandon flowlines per Rule 1103. File electronic Form 42 once abandonment complete.
40. Back fill hole with fill. Clean location, level.

TOC – 5930'

NB Top – 6783', SX Top – 3936', FHM – 680'

Offset to Iceman State 5-15HZ, Maverick State 4-15HZ, & Merlin 13-15HZ Pads in Top Gun Campaign Pasture

Gyro Completed 11/5/2014

No Known Casing Issues