

Document Number:
400815806

Date Received:
03/26/2015

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 47120 Contact Name: CHERYL LIGHT

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP Phone: (720) 929-6461

Address: P O BOX 173779 Fax: (720) 929-7461

City: DENVER State: CO Zip: 80217- Email: CHERYL.LIGHT@ANADARKO.COM

For "Intent" 24 hour notice required, Name: Carlile, Craig Tel: (970) 629-8279

COGCC contact: Email: craig.carlile@state.co.us

API Number 05-123-18854-00

Well Name: HSR-W.C.L. Well Number: 4-1

Location: QtrQtr: NWNW Section: 1 Township: 3N Range: 67W Meridian: 6

County: WELD Federal, Indian or State Lease Number: _____

Field Name: WATTENBERG Field Number: 90750

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.259500 Longitude: -104.846350

GPS Data:
Date of Measurement: 10/31/2006 PDOP Reading: 3.1 GPS Instrument Operator's Name: Steve Fisher

Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____

Casing to be pulled: Yes No Estimated Depth: 916

Fish in Hole: Yes No If yes, explain details below

Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7260	7266			
NIOBRARA	7035	7038			

Total: 2 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	712	500	712	0	VISU
1ST	7+7/8	3+1/2	7.7	7,400	200	7,400	6,518	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7005 with 20 sacks cmt on top. CIBP #2: Depth 80 with 25 sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 20 sks cmt from 7005 ft. to 6465 ft. Plug Type: CASING Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at 4488 ft. with 200 sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 160 sacks half in. half out surface casing from 1016 ft. to 612 ft. Plug Tagged:

Set 25 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

5 MIRU, kill as necessary using clean fresh water with biocide. ND WH. NU BOP. Unseat landing jt
6 POOH and stand back 2-1/16" tbg. (220 jts landed at 7230').
7 PU scraper for 3-1/2" 7.7# casing and RIH to 7050'. POOH and LD scraper.
8 MIRU wireline. PU 3-1/2" CIBP RIH and set at +/- 7005'. POOH and RD wireline
9 Notify Cementers to be on call.
10 RIH with 2-1/16" tbg RIH while hydrotesting to 3000 psi and tag CIBP set at 7005'. Record tag depth. Circulate gas out of the hole from just above tag depth.
11 MIRU cementers. Pump Nio balanced casing plug: Pump 20 sks of Cement Blend: "G" w/ 20% silica flour , 0.4% CD -32, 0.4% ASA -301 and R-3 to achieve 2:30 pump time mixed at 15.8 ppg and 1.38 cuft/sk designed for coverage above CIBP from 7005' to 6465'.
12 PUH 40 jts and circulate hole clean with fresh water and biocide. POOH standing back 130 jt.
13 MIRU WL. PU one 1', 2-1/2" perf gun w/ 0.49" diam, 120 phasing, 3 SPF and shoot 1' of squeeze holes at 4488'. RDMO WL.
14 Establish circulation down 3-1/2" casing through squeeze holes up 3-1/2" by 8-5/8" annulus to surface with water. If circulation is established, proceed to next step; otherwise contact engineering for revised procedure steps.
15 RU Cementers to 3-1/2" casing. Establish circulation, Pump Sussex plug: Pump 5 bbls fresh water followed by 20 bbls sodium metasilicate followed by 5 bbls fresh water ahead of cement: 200 sks (41 bbls) "G" w/ 0.25 pps cello flake, 0.4% CD-32, 0.4% ASA-301 with CaCl2 as necessary. Mixed at 15.8 ppg, 1.15 cuft/sack. Drop wiper plug and displace to 4088' using 37.4 bbls of water . Volume based on 10" x 3-1/2" annulus with 20% excess from 4488' to 4088', and 3-1/2" casing from 4488' to 4088'. RD Cementers.
16 RIH with 2-1/16" tbg to tag plug at +/- 4088'. . If cement is not at or above 4088' contact engineer, otherwise proceed to next step. POOH standing back 32 jts.
17 MIRU WL. Crack coupling or jet cut 3-1/2" csg at 916'. Circulate approximately 120 bbls of fresh water and biocide to remove any gas from wellbore.
18 ND BOP and tubing head. Install a BOP on surface casing head with 3-1/2" pipe rams. Install 3000 psi ball valves on both casing head outlets. Install a choke or choke manifold on one outlet.
19 POOH and LD 3-1/2" csg. Remove the 3-1/2" pipe rams and Install 2-1/16" pipe rams.
20 RIH w/ 2-1/16" WS open ended ~100' past the 3-1/2" csg stub to 1016'.
21 MIRU Cementers. Pump Fox Hills Balanced plug: Pump mud flush of 10 bbls SAPP followed by 20 bbls water ahead of 160 sks (37.8 bbls) Type III w/cello flake and CaCl2 as deemed necessary, mixed at 1.33 cf per sack, 14.8 ppg. POH and WOC per cementing company recommendation. Plug size is based on 3-1/2" casing from 1016' to 916' and 9" hole with 40% excess covering 916' to shoe of surface casing at 712' plus capacity of surface casing to 512'. PUH to 200' and Circulate out any excess cmt. TOH and WOC per cement company recommendation.
22 RIH and tag top of plug. Plug needs to be tagged at 612' or shallower. POOH and LD 2-1/16" tbg.
23 RU wireline. Run and set CIBP in the 8 5/8", 24# surface casing at 80'. PT CIBP and surface casing to 1000 psi for 15 minutes. Assuming successful test, RD wireline. RDMO workover rig.
24 Instruct cementing and wireline contractors to e-mail copies of all job logs/job summaries to rscDJVendors@anadarko.com within 24 hrs of completion of the job.
25 Supervisor submit paper copies of all invoices, logs, and reports to Evans Specialist.
26 Excavation crew to notify One Call to clear excavation area around wellhead and for flowlines.
27 Excavate hole around surface casing enough to allow welder to cut casing minimum 5' below ground level.
28 Welder cut casing minimum 5' below ground level.
29 Fill casing to surface using 4500 psi compressive strength cement, (NO gravel).
30 Spot weld on steel marker plate. Marker should contain Well name, Well number, legal location (1/4 1/4 descriptor) and API number.
31 Properly abandon flowlines p

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: CHERYL LIGHT
Title: SR. REGULATORY ANALYST Date: 3/26/2015 Email: DJREGULATORY@ANADARKO.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SCHLAGENHAUF, MARK Date: 4/21/2015

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: 10/20/2015

<u>COA Type</u>	<u>Description</u>
	1) Submit Form 42 electronically to COGCC 48 hours prior to MIRU. 2) If unable to pull casing contact COGCC for plugging modifications. 3) For 1016' plug: pump plug and displace, shut-in, WOC 4 hours and tag plug – must be 662' or shallower. 4) Properly abandon flowlines as per Rule 1103. File electronic Form 42 once abandonment complete. 5) Please submit existing gyro survey data with Form 6 (s) Subsequent Report of Abandonment.

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
400815806	FORM 6 INTENT SUBMITTED
400815811	PROPOSED PLUGGING PROCEDURE
400815812	WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	Well Completion Report dated 4/21/1995.	4/2/2015 9:28:53 AM

Total: 1 comment(s)