

WORKOVER PROCEDURE

WELL NAME: PETRIKIN A34-10 **DATE:** 4/30/2015

LOCATION: Qtr/Qtr: NW/SE Section: 34 Township: 6N Range: 64W

Footages: 1980' FSL & 1800' FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-13517

ENGINEER: Jonathan Pomerantz 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 302' KB Elevation: 4652'
Surface Cmt: 175 sx GL Elevation: 4641'
Long St Csg: 4 1/2" 15.1# @ 6959' TD: 6968'
Long St Cmt: 220 sx PBTD: 6901'
Long St Date: 12/13/1987

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6566' - 6764'
Perforation Interval (2): Codell Perforations 6829' - 6838'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# ? tbg @ 6796' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6516', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 850'. Pump 325 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.