

**WORKOVER PROCEDURE**

**WELL NAME:** UPV 31-07G3 **DATE:** 5/4/2015

**LOCATION:** Qtr/Qtr: SW/NE Section: 31 Township: 6N Range: 63W

Footages: 1934' FNL & 1935' FEL

**COUNTY:** WELD **STATE:** CO **API #:** 05-123-18976

**ENGINEER:** Jonathan Pomerantz 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 7" 17# @ 452' KB Elevation: 4645'  
Surface Cmt: 200 sx GL Elevation: 4631'  
Long St Csg: 3 1/2" 7.7# @ 6941' TD: 6962'  
Long St Cmt: 160 sx PBDT: 6881'  
Long St Date: 8/12/1995

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Codell Perforations 6771' - 6783'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 1/16" 3.25# J-55 tbg @ 6748' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_

**COMMENTS:** \_\_\_\_\_

**PROCEDURE:**

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 1/16" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6721'. RIH w/ workstring to CIBP @ 6721'. Pump 10 sx balance plug.
- 4) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 750'. Pump 175 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.