

WORKOVER PROCEDURE

WELL NAME: Stewart 1 **DATE:** 5/5/2015
LOCATION:
Qtr/Qtr: SW/SW Section: 32 Township: 5N Range: 65W
Footages: 600' FSL & 720' FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-12092

ENGINEER: Hilary Ramseier 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# 332' KB Elevation: 4685'
Surface Cmt: 250 sx GL Elevation: 4672'
Long St Csg: 4-1/2" 11.6# J-55 7207' TD: 7213'
Long St Cmt: 250 sx PBTD: 7178'
Long St Date: 11/24/1984

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6786' - 6934'
Perforation Interval (2): Codell Perforations 7118' - 7128'
Perforation Interval (3): _____
Tubing: 2-3/8" 4.7# J-55 7079' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: Currently not producing. No historical production.
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6736', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 435'. Pump 170 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.