

WORKOVER PROCEDURE

WELL NAME: Lilli Unit 6-6 DATE: 5/26/2015

LOCATION: Qtr/Qtr: SE/NW Section: 6 Township: 8N Range: 58W

Footages: 3085' FSL & 1780' FWL

COUNTY: WELD STATE: CO API #: 05-123-14022

ENGINEER: Ben Zapp PE 7 Day Notice Sent: (Please notify Engineer of any major changes prior to work) Do not start operations until: Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 260' KB Elevation: 4,808.00 Surface Cmt: 170 sx GL Elevation: 4,799.00 Long St Csg: 4 1/2" 10.5# @ 6618' TD: 6,618.00 Long St Cmt: 190 sx PBTD: ? Long St Date: 10/11/1988

Plug Back (Sand or CIBP): ?? Perforation Interval (1): D Sand 6,498' - 6,508' Perforation Interval (2): Perforation Interval (3): Tubing: 2 3/8" @ 6537' Rods: NA Pump: NA Misc.:

PRODUCTION STATUS: On Plunger Lift

COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) POOH w/ 2-3/8" tbg and lay down.
3) RU WL. RIH w/ CIBP. Set CIBP @ 6,448', dump bail 2 sx of cement on top.
4) RIH and pump 10sxs over Nio top at 5,768'
5) Unland casing. Cut casing off @ 2,500'. POOH with casing laying down on trailer.
6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
7) POOH w/ workstring to 845'. Pump 325 sx shoe plug. Cement to surface. (Water well at 695')
8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
9) Cut surface casing off 6'-8' below ground.
10) Clean up location. Reclaim location. RDMO.