

WORKOVER PROCEDURE

WELL NAME: Wells Ranch USX AA25-10 **DATE:** 5/27/2015
LOCATION:
Qtr/Qtr: NWSE Section: 25 Township: 6N Range: 63W
Footages: 2007 FSL & 1949 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-25738

ENGINEER: BRIAN ULMER 7 Day Notice Sent:
(Please notify Engineer of any major Do not start operations until:
changes prior to work) Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# J-55 @ 478 KB Elevation: 4,739'
Surface Cmt: 225 sx GL Elevation: 4,726'
Long St Csg: 4-1/2" 11.6# M-80 @ 6,810' TD: 6,810'
Long St Cmt: 330 sx PBTD: 6,754'
Long St Date: 5/10/2008

Plug Back (Sand or CIBP):

Perforation Interval (1): Niobrara Perforations: 6,380' - 6,396'; 6,477' - 6,493'

Perforation Interval (2): Codell Perforations: 6,648' - 6,659'

Perforation Interval (3):

Tubing: None Rods:

Pump:

Misc.:

PRODUCTION STATUS: No production since June 2013

COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) RU WL. Dump bail 2 sx cement on top of Retrievable Bridge Plug set at 6330' on 12/30/2011.
- 3) RIH w/ workstring to 2500'. Pump 20 sx balance plug. SI, WOC. If circulation maintained no need to tag plug.
- 4) Unland casing. Cut casing off @ 1600'. POOH w/ csg laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 650'. Pump 240 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cmt if needed.
- 8) Cut surface casing off 6-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.