

WORKOVER PROCEDURE

WELL NAME: EMBREE 10-03 **DATE:** 6/2/2015

LOCATION: Qtr/Qtr: NE/NW Section: 10 Township: 4N Range: 64W

Footages: 659' FNL & 1979' FWL

COUNTY: WELD **STATE:** CO **API #:** 05-123-17581

ENGINEER: Jonathan Pomerantz 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 7" 17# @ 511' KB Elevation: 4674'
Surface Cmt: 286 sx GL Elevation: 4661'
Long St Csg: 3 1/2" 7.7# @ 6988' TD: 7020'
Long St Cmt: 150 sx PBTD: 6944'
Long St Date: 12/21/1993

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 6800' - 6812'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 1/16" 3.25# @ 6779' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 1/16" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6750'. RIH w/ workstring to 6750'. Pump 20 sx balance plug on top of CIBP.
- 4) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 620'. Pump 250 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.