

WORKOVER PROCEDURE

WELL NAME: Moser H34-21 DATE: 6/23/2015

LOCATION: Qtr/Qtr: SE/NW Section: 34 Township: 3N Range: 65W

Footages: 2416' FNL & 2418' FWL

COUNTY: WELD STATE: CO API #: 05-123-26310

ENGINEER: Benjamin Daniell 7 Day Notice Sent: (Please notify Engineer of any major changes prior to work) Do not start operations until: Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# J-55 @ 748' KB Elevation: 4842.5' Surface Cmt: 308 sx GL Elevation: 4830' Long St Csg: 4 1/2" 11.6# M-80 @ 7271' TD: 7283' Long St Cmt: 430 sx PBSD: 7253' Long St Date: 10/14/2007

Plug Back (Sand or CIBP): Perforation Interval (1): Niobrara Perforations 6919'-6935' Perforation Interval (2): Codell Perforations 7127'-7141' Perforation Interval (3): Tubing: 2 3/8" 4.7# J-55 @ 7112' Rods: Pump: Misc.:

PRODUCTION STATUS: SI; Hole in fire tube COMMENTS: Oil to surface

- PROCEDURE: 1) MIRU Workover rig, pump & tank. 2) POOH w/ 2 3/8" tbg and lay down. 3) RU WL. RIH w/ CIBP. Set CIBP @ 6869', dump bail 2 sx of cement on top. 4) Unland casing. Cut casing off @ 1950'. POOH with casing laying down on trailer. 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug. 6) POOH w/ workstring to 848'. Pump 265 sx shoe plug. Cement to surface. 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed. 8) Cut surface casing off 6'-8' below ground. 9) Clean up location. Reclaim location. RDMO.