

WORKOVER PROCEDURE

WELL NAME: REINICK 09-07 DATE: 6/25/2015

LOCATION: Qtr/Qtr: SW/NE Section: 9 Township: 4N Range: 64W

Footages: 1978' FNL & 1981' FEL COUNTY: WELD STATE: CO API #: 05-123-17360

ENGINEER: Jonathan Pomerantz 7 Day Notice Sent: (Please notify Engineer of any major changes prior to work) Do not start operations until: Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 23# @ 457' KB Elevation: 4704' Surface Cmt: 300 sx GL Elevation: 4693' Long St Csg: 4 1/2" 11.6# @ 7019' TD: 7034' Long St Cmt: 175 sx + 255 sx PBDT: 6908' Long St Date: 9/19/1993

Plug Back (Sand or CIBP): Perforation Interval (1): Niobrara Perforations 6576' - 6741' Perforation Interval (2): Codell Perforations 6860' - 6872' Perforation Interval (3): Tubing: 2 3/8" 4.7# J-55 tbg @ 6847' Rods: Pump: Misc.:

PRODUCTION STATUS: COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank. 2) POOH w/ 2 3/8" tbg and lay down. 3) RU WL. RIH w/ CIBP. Set CIBP @ 6526', dump bail 2 sx of cement on top. 4) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer. 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug. 6) POOH w/ workstring to 560'. Pump 200 sx shoe plug. Cement to surface. 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed. 8) Cut surface casing off 6'-8' below ground. 9) Clean up location. Reclaim location. RDMO.