

Document Number:
 400844329
 Date Received:
 05/26/2015

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.
 A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 47120 Contact Name: Cheryl Light
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP Phone: (720) 929-6461
 Address: P O BOX 173779 Fax: (720) 929-7461
 City: DENVER State: CO Zip: 80217- Email: cheryl.light@anadarko.com
For "Intent" 24 hour notice required, Name: Carlile, Craig Tel: (970) 629-8279
COGCC contact: Email: craig.carlile@state.co.us

API Number 05-123-15289-00 Well Name: CLIFFORD Well Number: L3-6
 Location: QtrQtr: SENW Section: 3 Township: 3N Range: 66W Meridian: 6
 County: WELD Federal, Indian or State Lease Number: _____
 Field Name: WATTENBERG Field Number: 90750

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.255370 Longitude: -104.765200
 GPS Data:
 Date of Measurement: 06/28/2006 PDOP Reading: 1.9 GPS Instrument Operator's Name: Paul Tappy
 Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____
 Casing to be pulled: Yes No Estimated Depth: 4590
 Fish in Hole: Yes No If yes, explain details below
 Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
 Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7308	7323			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	411	230	411	10	VISU
1ST	7+7/8	2+7/8	7.9	7,453	300	7,453	6,460	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7250 with 20 sacks cmt on top. CIBP #2: Depth 80 with 25 sacks cmt on top.
 CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
 CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 20 sks cmt from 7250 ft. to 6230 ft. Plug Type: CASING Plug Tagged:
 Set 450 sks cmt from 4590 ft. to 3990 ft. Plug Type: OPEN HOLE Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
 Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)
 Set 540 sacks half in. half out surface casing from 1050 ft. to 311 ft. Plug Tagged:
 Set 25 sacks at surface
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
 Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____
 *Wireline Contractor: _____ *Cementing Contractor: _____
 Type of Cement and Additives Used: _____
 Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

- Step
 Description of Work
 1 Provide 48 hr notice to COGCC prior to rig up per request on approved Form 6 (e.g. call field coordinator, submit Form 42, etc.). Call the Automation Removal Group at least 24 hr prior to rig move. Request they catch and remove plunger, isolate production equipment and remove any automation prior to rig MIRU.
 2 MIRU slickline services. Pull bumper spring and tag bottom.
 3 Check and report surface casing pressure. If surface casing is not accessible at ground level, re-plumb so valve is at ground level.
 4 Prepare location for base beam equipped rig. Install perimeter fence as needed.
 5 MIRU, kill well as necessary using clean fresh water with biocide. ND WH. NU BOP. Unseat landing jt.
 6 TOOH and stand back 1.66" IJ tbg: 222 jts total landed @ 7271'
 7 MIRU WL. RIH w/ gauge ring for 2 7/8" 7.9# tbg to 7300'. RIH 2 7/8" CIBP and set at 7250' to abandon Codell perms. Pressure test plug and csg to 3000 psi for 15 minutes.
 8 RIH 1.66" tbg open-ended to CIBP @ 7250'. Hydro-test tbg to 3000 psi.
 9 RU cementers and equalize a balanced plug above RBP from 7250' to 6230' as follows: 20 sx "Thermal 35" + 0.5% CFR-2 + 0.25% FMC, mixed at 15.6 ppg and 1.51 cuft/sk. (30 cuft of slurry).
 10 Pull and LD tbg to ~6000' and reverse circulate clean w/fresh water treated with biocide.
 11 TOOH and LD 1.66" tbg.
 12

RU WL, RIH w/ chemical cutter or jet cutter and cut 2 7/8" casing at 4590'. Circulate bottoms up and continue circulating to remove any gas from wellbore. RD WL.

13

ND BOP and wellhead. Install BOP on surface casing head with 2 7/8" pipe rams. Install 3000 psi ball valves on both casing head outlets. Install a choke or choke manifold on one outlet. NOTE: If 2 7/8" csg did not pass PT in step #7, TOO and hydro-test in to 3000 psi before proceeding to step 14.

14

RU Cementers. Establish circulation down 2 7/8" csg taking returns on surface csg. Pump 5 bbl water w/ biocide, 20 bbl Sodium Metasilicate, and another 5 bbl spacer immediately preceding cement. Note: If unable to circulate, consult Evans Engineering.

15

Pump a balanced cement plug from 4590' to 3990': 450 sx class "G" w/0.25 lb/sk Polyflake 0.5% CFR-2, 0.2% FMC, 0.5% LWA mixed at 15.8 ppg and 1.15 cf/sk. (518 cuft of slurry). Cement volume based on 600' coverage in 11 1/2" open hole with 20% excess.

16

TOH to 2000' and circulate to clear 2 7/8" and wellbore. WOC per cementing company recommendation.

17

TIH and tag top of plug @ 3990'. Lay down 2 7/8" to place EOT at 1050'.

18

Establish circulation and circulate bottoms up.

19

RU cementers. Pump 10 bbl SAPP (Sodium Acid Pyrophosphate) followed by 20 bbl (min) fresh water spacer immediately preceding cement.

20

Pump a balanced plug 1050'-211': 540 sx (718 cuft.) Type III cement w/ 0.25 pps Polyflake, 0.3% CFR-2, 0.3% CFL-3 and 0.5% CaCl2 mixed at 14.8 ppg and 1.33 cf/sk. Design to fill 639' in 11.5" OH + 40% excess and 200' in 8 5/8" surface casing.

21

TOOH and LD 2 7/8" tbg. WOC per cementing company recommendation. Tag plug; TOC should be 311' or higher. If not, Consult Evans Engineering before proceeding.

22

MIRU WL. RIH 8 5/8" CIBP to 80'. Set and PT to 1000 psi for 15 min. If tests, RDMO WL and WO rig.

23

Instruct cementing and wireline contractors to e-mail copies of all job logs/job summaries to rscDJVendors@anadarko.com within 24 hrs of completion of the job.

24

Supervisor submit paper copies of all invoices, logs, and reports to Evans Engineering Specialist.

25

Excavation crew to notify One Call to clear excavation area around wellhead and for flowlines.

26

Excavate hole around surface casing enough to allow welder to cut 8 5/8" casing minimum 5' below ground level.

27

Welder cut 8 5/8" casing minimum 5' below ground level.

28

Fill casing to surface using 4500 psi compressive strength cement, (NO gravel).

29

Spot weld on steel marker plate. Marker should contain Well name, Well number, legal location (1/4 1/4 descriptor) and API number.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Cheryl Light

Title: Sr. Regulatory Analyst Date: 5/26/2015 Email: cheryl.light@anadarko.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SCHLAGENHAUF, MARK Date: 6/28/2015

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: 12/27/2015

COA Type	Description
	1) Submit Form 42 electronically to COGCC 48 hours prior to MIRU. 2) If unable to pull casing below 4000' contact COGCC for plugging modifications. 3) For 1050' plug: pump plug and displace, shut-in, WOC 4 hours and tag plug – must be 361' or shallower. 4) Properly abandon flowlines as per Rule 1103. File electronic Form 42 once abandonment complete. 5) Please submit existing gyro survey data with Form 6 (s) Subsequent Report of Abandonment. 6) No open hole logs on file. Please submit open hole logs (DIL/SFL-GR, FDC, CD-GR) with Form 6 (s) Subsequent Report of Abandonment or file them attached to a form 4 sundry.

Attachment Check List

Att Doc Num	Name
400844329	FORM 6 INTENT SUBMITTED
400844342	WELLBORE DIAGRAM
400844343	PROPOSED PLUGGING PROCEDURE

Total Attach: 3 Files

General Comments

User Group	Comment	Comment Date
Permit	Well Completion Report dated 12/5/1991.	5/29/2015 9:28:06 AM

Total: 1 comment(s)