

WORKOVER PROCEDURE

WELL NAME: Goodner 06-01 **DATE:** 6/30/2015

LOCATION:
Qtr/Qtr: NE/SE Section: 6 Township: 4N Range: 65W
Footages: 1980' FSL & 660' FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-13912

ENGINEER: Hilary Ramseier 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# @ 430' KB Elevation: 4,695'
Surface Cmt: 450 sx GL Elevation: 4,685'
Long St Csg: 4-1/2" 11.6# N-80 @ 7,350' TD: 7,351'
Long St Cmt: 230 sx PBTD: 7,211'
Long St Date: 4/13/2015

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7,186' - 7,199'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2-3/8" 4.7# J-55 @ 7,167' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: Currently producing 0.75 bopd and 20 mcf. Pressures currently 369/373

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7,136'. ROOH.
- 4) RIH w/ workstring to pump 30 sx on top of the CIBP @ 7,136' (need to cover 100' above top of Nio)
- 5) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 7) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 8) POOH w/ workstring to 530'. Pump 205 sx shoe plug. Cement to surface.
- 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.