

## WORKOVER PROCEDURE

<b>WELL NAME:</b>	UPV 31-09G3		<b>DATE:</b>	7/20/2015			
<b>LOCATION:</b>							
Qtr/Qtr:	NESE	Section:	31	Township:	6N	Range:	63W
Footages:	1988	FSL	&	645	FEL		
<b>COUNTY:</b>	WELD		<b>STATE:</b>	CO		<b>API #:</b>	05-123-18869
<b>ENGINEER:</b>	BRIAN ULMER		7 Day Notice Sent:				
	(Please notify Engineer of any major changes prior to work)		Do not start operations until:				
			Notice Expires:				
<b>OBJECTIVE:</b>	P&A						
<b>WELL DATA:</b>							
Surface Csg:	7" 17# H-40 @ 452'			KB Elevation:	4656'		
Surface Cmt:	200 sx			GL Elevation:	4645'		
	3-1/2" 7.7# M-75 @ 5,820' 2-7/8" 6.4# J-55 @						
Long St Csg:	5,820'-6920'			TD:	6954'		
Long St Cmt:	185 sx			PBTD:	6787'		
Long St Date:	2/5/1995						
Plug Back (Sand or CIBP):							
Perforation Interval (1):	Niobrara Perforations: 6,560' - 6,588'; 6,646' - 6,654'						
Perforation Interval (2):	Codell Perforations: 6,738' - 6,758'						
Perforation Interval (3):							
Tubing:	None		Rods:				
Pump:							
Misc.:							
<b>PRODUCTION STATUS:</b>	No sustained production since November 2014						
<b>COMMENTS:</b>	PBTD may be 6888'. Records have conflicting data with likely mistake.						

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) Unflange WH and POOH with production tubing.
- 3) RU WL. RIH w/ 2-7/8" CIBP and set @ 6510'. Dump bail 2 sx cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH w/ csg laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 750'. Pump 154 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cmt if needed.
- 8) Cut surface casing off 6-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.