

WORKOVER PROCEDURE

WELL NAME: Anacapa 32-31 **DATE:** 7/31/2015
LOCATION:
Qtr/Qtr: SW/NE Section: 31 Township: 2N Range: 64W
Footages: 2196' FNL & 1513' FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-22116

ENGINEER: Benjamin Daniell **7 Day Notice Sent:** _____
(Please notify Engineer of any major changes prior to work) **Do not start operations until:** _____
Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# J-55 @ 995' **KB Elevation:** 4987'
Surface Cmt: 650 sx **GL Elevation:** 4972'
Long St Csg: 4 1/2" 11.6# I-80 @ 7819' **TD:** 7825'
Long St Cmt: 200 sx **PBTD:** 7800'
Long St Date: 1/22/2005

Plug Back (Sand or CIBP): _____
Perforation Interval (1): J Sand Perforations 7636' - 7674'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 @ 7610' **Rods:** _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: SI; Flowline leak
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7586', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring and pump 10 sx balance plug at 6931'. If maintain curculation, no need to tag plug.
- 5) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 1095'. Pump 345 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.