

## WORKOVER PROCEDURE

**WELL NAME:** BOULTER 31-01 **DATE:** 8/20/2015  
**LOCATION:**  
Qtr/Qtr: SW/NE Section: 31 Township: 5N Range: 64W  
Footages: 1980' FNL & 1991' FEL  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-11911

**ENGINEER:** Jonathan Pomerantz 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 423' KB Elevation: 4784'  
Surface Cmt: 165 sx GL Elevation: 4772'  
Long St Csg: 4 1/2" 11.6# @ 7135' TD: 7160'  
Long St Cmt: 190 sx PBTD: 7097'  
Long St Date: 8/25/1984

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Codell Perforations 7011' - 7022'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8" 4.7# J-55 tbg @ 6951' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6961'. RIH w/ workstring to 6960' (CIBP). Pump 35 sx cement on top of CIBP.
- 4) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 530'. Pump 200 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.