

WORKOVER PROCEDURE

WELL NAME: Boedecker 40 **DATE:** 8/20/2015

LOCATION:
Qtr/Qtr: CSW Section: 22 Township: 2N Range: 64W
Footages: 1320' FSL & 1320' FWL

COUNTY: WELD **STATE:** CO **API #:** 05-123-07818

ENGINEER: Benjamin Daniell 7 Day Notice Sent: _____
(Please notify Engineer of any major changes prior to work) Do not start operations until: _____
Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# K-55 @ 854' KB Elevation: 5006
Surface Cmt: 649 sx GL Elevation: 4993'
Long St Csg: 4 1/2" 11.6# K-55 @ 7714' TD: 7716'
Long St Cmt: 197 sx PBTD: 7682'
Long St Date: 8/26/1973

Plug Back (Sand or CIBP): _____
Perforation Interval (1): J-Sand Perforations 7586' - 7610'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 1.9" 2.9# WPC W-55 @ 7561" Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: Producing
COMMENTS: LOE loser, won't cover AF for WBI

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1.9" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7536', dump bail 2 sx of cement on top.
- 4) RIH w/ guns. Perforate casing @ 6624' and 6474'.
- 5) RIH w/ CICR and set @ 6524'.
- 6) RIH w/ workstring and sting into CICR. Pump 50 sx through and 5 sx on top.
- 7) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 8) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 9) POOH w/ workstring to 1110'. Pump 365 sx shoe plug. Cement to surface.
- 10) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 11) Cut surface casing off 6'-8' below ground.
- 12) Clean up location. Reclaim location. RDMO.