

## WORKOVER PROCEDURE

**WELL NAME:** Gordon 1261-28-32 **DATE:** 8/24/2015  
**LOCATION:** Qtr/Qtr: NWSW Section: 28 Township: 12N Range: 61W  
Footages: 1980' FSL & 660' FWL  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-30305

**ENGINEER:** Ben Zapp PE 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# J-55 @ 1056' KB Elevation: 5247'  
Surface Cmt: 230 sx GL Elevation: 5235'  
Long St Csg: 5 1/2" 17# N-80 @ 7885' TD: 7900'  
Long St Cmt: 1130 sx PBTD: 7852'  
Long St Date: 4/17/2010

Plug Back (Sand or CIBP): \_\_\_\_\_

	Zone	Top Perf	Bottom Perf
Perforation Interval (1):	J Sand	7714'	7735'
Perforation Interval (2):			
Perforation Interval (3):			

Tubing: 2 7/8" 6.5# J55 Rods: Yes  
Pump: \_\_\_\_\_  
Misc.: TA set @ 7,606ft

**PRODUCTION STATUS:** SI  
**COMMENTS:** Lost Lease

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ pump, rods and 2 7/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7664', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to pump 15 sx (100ft) plug at 6820ft (Nio Top) . If maintain circulation, no need to tag plug.
- 5) POOH w/ workstring to 2500'. Pump 50 sx courtesy plug. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 1156'. Pump 150 sx shoe plug to surface. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.