

PLUG AND ABANDONMENT PROCEDURE

Engineer: David Dalton

Cell: 970-590-6245

LULU XX08-14D

Step	Description of Work
1	Provide 48 hr notice to COGCC prior to rig up per request on approved Form 6 (e.g. call field coordinator, submit Form 42, etc.).
2	Prepare location for base beam equipped rig. Install perimeter fence as needed.
3	Check and report surface casing pressure. If surface casing is not accessible at ground level, re-plumb so valve is at ground level.
4	MIRU service unit. NU BOP on surface casing head. PU and TIH 2 3/8" tbg WS open ended to PBTD @ 1041'. Hydro -test tbg to 3000 psi.
5	RU cementers. Pump a balanced Plug from 1041' to surface: 270 sx Type III cement mixed at 14.8 ppg and 1.33 cf/sx (359 cuft of slurry).
6	LD work string. RDMO service unit.
7	Instruct cementing and wireline contractors to e-mail copies of all job logs/job summaries to rscDJVendors@anadarko.com within 24 hrs of completion of the job.
8	Supervisor submit paper copies of all invoices, logs, and reports to Evans Engineering Specialist.
9	Excavation crew to notify One Call to clear excavation area around wellhead and for flowlines.
10	Excavate hole around surface casing enough to allow welder to cut 8 5/8" casing minimum 5' below ground level.
11	Welder cut casing minimum 5' below ground level.
12	Fill casing to surface using 4500 psi compressive strength cement, (NO gravel).
13	Spot weld on steel marker plate. Marker should contain Well name, Well number, legal location (1/4 1/4 descriptor) and API number.
14	Obtain GPS location data as per COGCC Rule 215 and send to rscDJVendors@anadarko.com.
15	Properly abandon flowlines per Rule 1103. File electronic Form 42 once abandonment complete.
16	Back fill hole with fill. Clean location, level.
17	Submit Form 6 to COGCC ensuring to provide 'As performed' WBD identifying operations completed.