

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400891802

Date Received:

08/28/2015

Spill report taken by:

LUJAN, CARLOS

Spill/Release Point ID:

442971

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: OXY USA INC Operator No: 66561 Address: 760 HORIZON DR #101 City: GRAND JUNCTION State: CO Zip: 81506 Contact Person: Blair Rollins Phone Numbers: Phone: (970) 263-3637 Mobile: (970) 640-6919 Email: blair_rollins@oxy.com

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400887236

Initial Report Date: 08/20/2015 Date of Discovery: 08/19/2015 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR SENE SEC 7 TWP 10S RNG 94W MERIDIAN 6

Latitude: 39.206106 Longitude: -107.917612

Municipality (if within municipal boundaries): County: MESA

Reference Location:

Facility Type: WELL PAD Facility/Location ID No 334514 No Existing Facility or Location ID No. Well API No. (Only if the reference facility is well) 05-

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0 Estimated Condensate Spill Volume(bbl): 0 Estimated Flow Back Fluid Spill Volume(bbl): 0 Estimated Produced Water Spill Volume(bbl): 0 Estimated Other E&P Waste Spill Volume(bbl): >=5 and <100 Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: Produced water and tank bottom sludge

Land Use:

Current Land Use: NON-CROP LAND Other(Specify): Weather Condition: Sunny Surface Owner: FEE Other(Specify): OXY USA Inc.

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State [X] Residence/Occupied Structure [] Livestock [X] Public Byway [] Surface Water Supply Area [] As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

At approximately 1:00PM on Wednesday (August 19, 2015) an Oxy contract hydrovac operator spilled approximately 10 barrels of produced water and tank bottom sludge outside of secondary containment during hydrovac unloading operations. During unloading activities, the back gate of the hydrovac truck lost hydraulic pressure and unexpectedly opened. The spilled material flushed out of the hydrovac truck, exited the lined secondary containment, and flowed down the fill slope off the pad and into a small stormwater diversion ditch and stormwater sediment pond. Oxy personnel and contractors immediately contained the running water within the ditch downgradient of the impacted area and began removing the liquid. Another onsite contractor immediately diverted the flowing water upgradient of the impacted area to aid in isolating and capturing all impacted soil and surface water. Impacted soil and water was removed and reintroduced into the secondary containment for disposal.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
8/20/2015	COGCC	Carlos Lujan	970-625-2497	No response yet
8/20/2015	Mesa County	Andrew Martsoff	970-244-1763	No response yet

SPILL/RELEASE DETAIL REPORTS

#1 Supplemental Report Date: 08/28/2015

FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	0	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	10	10	<input type="checkbox"/>

specify: Produced water and tank bottom sludge

Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit

Impacted Media (Check all that apply) Soil Groundwater Surface Water Dry Drainage Feature

Surface Area Impacted: Length of Impact (feet): 30 Width of Impact (feet): 20
 Depth of Impact (feet BGS): 0 Depth of Impact (inches BGS): 2

How was extent determined?

Extent of contamination was determined visually and screened by using a PID. Surface water was contained downgradient of the impacted area and removed for offsite disposal. Confirmation soil sampling has been coordinated with a third party contractor but will not be completed until 8/31/2015. Oxy will provide the results of the confirmation sampling and summary of activities report in a supplemental Form 19 for COGCC review and approval.

Soil/Geology Description:

Cerro silty clay loam, 2 - 6 percent slopes

Depth to Groundwater (feet BGS) 40 Number Water Wells within 1/2 mile radius: 1
 If less than 1 mile, distance in feet to nearest Water Well 2662 None Surface Water 50 None
 Wetlands 3034 None Springs None
 Livestock 150 None Occupied Building 2155 None

Additional Spill Details Not Provided Above:

CORRECTIVE ACTIONS

#1	Supplemental Report Date:	08/28/2015	
Cause of Spill (Check all that apply) <input checked="" type="checkbox"/> Human Error <input checked="" type="checkbox"/> Equipment Failure <input type="checkbox"/> Historical-Unknown			
<input type="checkbox"/> Other (specify) _____			
Describe Incident & Root Cause (include specific equipment and point of failure)			
The point of failure was the airplane wing located on the left side of the rear hatch door. The airplane wings (door lock system) would not move, allowing the door hinge system to malfunction and lose hydraulic control of the rear door. The door unexpected opened completely and released the contents of the hydrovac truck all at once.			
Describe measures taken to prevent the problem(s) from reoccurring:			
The equipment was taken out of service to ensure all mechanical issues were fixed with the door hinge system. During unloading activities, all malfunctioning airplane wings will be monitored to ensure proper unloading activities are completed.			
Volume of Soil Excavated (cubic yards): <u> 2 </u>			
Disposition of Excavated Soil (attach documentation) <input checked="" type="checkbox"/> Offsite Disposal <input type="checkbox"/> Onsite Treatment			
<input type="checkbox"/> Other (specify) _____			
Volume of Impacted Ground Water Removed (bbls): <u> 0 </u>			
Volume of Impacted Surface Water Removed (bbls): <u> 5 </u>			

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: Corrective Actions Completed (documentation attached)

Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Blair Rollins

Title: HES Specialist Date: 08/28/2015 Email: blair_rollins@oxy.com

Attachment Check List

Att Doc Num	Name
400891852	AERIAL PHOTOGRAPH
400891853	TOPOGRAPHIC MAP

Total Attach: 2 Files

General Comments

User Group	Comment	Comment Date

Total: 0 comment(s)