

WORKOVER PROCEDURE

WELL NAME: State #16-6 **DATE:** 8/28/2015
LOCATION:
Qtr/Qtr: NWSW Section: 16 Township: 4N Range: 67W
COUNTY: Morgan **STATE:** CO **API #:** 05-123-13909

ENGINEER: 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: Plug & Abandon

WELL DATA: Surface Csg: 9 5/8" 40# @ 320' KB Elevation: 4890'
Surface Cmt: 225 sacks cement GL Elevation: 4880'
Long St Csg: 2 7/8" 6.5# @ 7333 TD: 7335'
Long St Cmt: 450 sacks cement PBTD: 7335'
Long St Date: _____

Plug Info (1) CIBP @ 6865' w/ 2sx on top
Plug Info (2) 5700' - 5800' w/ 45sx
Plug Info (3) 3300' - 3400' w/ 45sx
Plug Info (4) 420' - Surface w/ 350sx - 150sx in, 200sx out

Tubing: _____ Rods: _____
Pump: _____
Misc.: Niobrara-Codell: 6915' - 7247'

WELL STATUS: _____

COMMENTS: Spud Date:3/30/1988 TOC: Unkown

PROCEDURE:

- 1) MIRU and blow well down.
- 2) RIH with CIBP set @ 6865' with 2sx Class G cement on top.
- 3) Cut 2 7/8" casing @ 5700' set stub plug with 45sx, set and tag plug.
- 4) Set open hole plug with 45sx @ 3300', set and tag plug.
- 5) Cut surface casing 5' below surface.
- 6) Pump 350sx @ 420', 150sx in, 200sx out.
- 7) RDMO.
- 8) Weld cap on and reclaim surface.