

WORKOVER PROCEDURE

WELL NAME: Gray 10-6 **DATE:** 9/1/2015

LOCATION: Qtr/Qtr: NW/SE Section: 6 Township: 2N Range: 64W

Footages: 1927' FSL & 2033' FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-20989

ENGINEER: Benjamin Daniell 7 Day Notice Sent: _____

(Please notify Engineer of any major Do not start operations until: _____

changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# J-55 @ 763' KB Elevation: 4855'

Surface Cmt: 535 sx GL Elevation: 4843'

Long St Csg: 4 1/2" 11.6# I-70 @ 7847' TD: 7857'

Long St Cmt: 250 sx PBDT: 7830'

Long St Date: 9/25/2002

Plug Back (Sand or CIBP): _____

Perforation Interval (1): Niobrara Perforations 6842' - 6960'

Perforation Interval (2): Codell Perforations 7078' - 7094'

Perforation Interval (3): J Sand Perforations 7554' - 7584' (Abandoned)

Perforation Interval (4): Dakota Perforations 7734' - 7744' (Abandoned)

Tubing: 2 3/8" 4.7# J-55 @ '6840 Rods: _____

Pump: _____

Misc.: _____

PRODUCTION STATUS: Producing; Doesn't cover STEM work.

COMMENTS: Tubing set depth is not in the well file. Just an FYI there might be more or less tubing.

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6793', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 4500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 150 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 863'. Pump 275 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.