

WORKOVER PROCEDURE

WELL NAME: Croissant 27-04G6 **DATE:** 9/1/2015
LOCATION:
Qtr/Qtr: NW/NW Section: 27 Township: 6N Range: 66W
Footages: 661 FSL: & 1962 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-18600

ENGINEER: John Hatch 7 Day Notice Sent: _____
(Please notify Engineer of any major changes prior to work) Do not start operations until: _____
Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 7" 17# H-40 @460' KB Elevation: 4760'
Surface Cmt: 200 sx GL Elevation: 4749'
Long St Csg: 4 1/2" 11.60# I-80 @7259' TD: 7259'
Long St Cmt: 200 sx PBTD: 7202'
Long St Date: 10/22/1994

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Cordell Perforations 7118' - 7138'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" 4.70# J-55 @7084.13' Rods: N/A
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7068', pump 35 sxs of cement
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 660'. Pump 140 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. RDMOL.