

WORKOVER PROCEDURE

WELL NAME: Faramir Farms 06-22 **DATE:** 9/8/2015

LOCATION: Qtr/Qtr: SW/NW/NW Section: 6 Township: 3N Range: 64W

Footages: 760' FNL & 460' FWL

COUNTY: WELD **STATE:** CO **API #:** 05-123-19812

ENGINEER: Benjamin Daniell 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# J-55 @ 666' KB Elevation: 4861'
Surface Cmt: 460 sx GL Elevation: 4851'
Long St Csg: 4 1/2" 11.6# N-80 @ 7243' TD: 7257'
Long St Cmt: 725 sx PBTD: 7201'
Long St Date: 10/24/1999

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6818' - 6893'
Perforation Interval (2): Codell Perforations 7090' - 7100' (Abandoned)
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 @ 6802' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: Producing

COMMENTS: Doesn't cover battery relocate for CR 49 Expansion

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6768', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 25 sx balance plug @ 4640'. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 766'. Pump 240 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.