

**WORKOVER PROCEDURE**

**WELL NAME:** Eisenman 22-15 **DATE:** 9/11/2015

**LOCATION:**  
Qtr/Qtr: SE/NW Section: 15 Township: 5N Range: 65W  
Footages: 2100 FNL & 2170 FWL

**COUNTY:** WELD **STATE:** CO **API #:** 05-123-17552

**ENGINEER:** John Hatch 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 445' KB Elevation: 4645'  
Surface Cmt: 285 sx GL Elevation: 4635'  
Long St Csg: 2 7/8" 6.50# N-80 @ 7167' TD: 7198'  
Long St Cmt: 225 sx PBTD: 7131'  
Long St Date: 11/13/1993

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Niobrara Perforations 6854' - 6860'  
Perforation Interval (2): Codell Perforations 7025' - 7035'  
Perforation Interval (3): Codell Perforations 7026' - 7032'  
Tubing: \_\_\_\_\_ Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

**PROCEDURE:**

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6804', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 495'. Pump 172 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. RDMOL.