

WORKOVER PROCEDURE

WELL NAME: Petrikin A34-11 **DATE:** 10/1/2015

LOCATION:
Qtr/Qtr: NE/SW Section: 34 Township: 6N Range: 64W
Footages: 1980' FSL & 1980' FWL

COUNTY: WELD **STATE:** CO **API #:** 05-123-13530

ENGINEER: NARAYAN CHOUDHARY 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# J-55 @ 299' KB Elevation: 4650'
Surface Cmt: 110 sx GL Elevation: 4639'
Long St Csg: 4 1/2" 15.1# N-80 @ 6962' TD: 6997'
Long St Cmt: 230 sx PBTD: 6905'
Long St Date: 12/22/1987

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6514' - 6708'
Perforation Interval (2): Codell Perforations 6816' - 6825'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 @ 6787' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: Producing

COMMENTS: Doesn't cover STEM work

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6464', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 850'. Pump 260 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.