

WORKOVER PROCEDURE

WELL NAME: Riva Red D31-3 **DATE:** 10/5/2015
LOCATION:
Qtr/Qtr: NE/NW Section: 31 Township: 3N Range: 64W
Footages: 510' FNL & 1985 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-16670

ENGINEER: Benjamin Daniell 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# @ 613' KB Elevation: 4816'
Surface Cmt: 500 sx GL Elevation: 4803'
Long St Csg: 3-1/2" 9.3# @ 7205' TD: 7221'
Long St Cmt: 600 sx PBTD: 7204'
Long St Date: 1/14/1993

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Sussex Perforations 4392' - 4416' (Squeezed 12/14/05)
Perforation Interval (2): Codell Perforations 7048' - 7058'
Perforation Interval (3): _____
Tubing: 2-1/16" 3.25# J-55 @ 7021' Rods: NA
Pump: NA
Misc.: _____

PRODUCTION STATUS: Producing
COMMENTS: Doesn't pay for CR49 expansion

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 1/16" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6998', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to pump 100 sx balance plug @ 6768' to cover nio top. If maintain circulation, no need to tag plug.
- 5) POOH w/ work string to 4566'. Pump 15 sx balance plug. If maintain circulation, no need to tag plug.
- 6) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 7) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 8) POOH w/ workstring to 751'. Pump 250 sx shoe plug. Cement to surface.
- 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. Reclaim location. RDMO.