

WORKOVER PROCEDURE

WELL NAME: BROWN-DAVEE 01-34 **DATE:** 10/7/2015

LOCATION: Qtr/Qtr: NE/NE Section: 34 Township: 6N Range: 66W

Footages: 678 FNL & 862 FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-11916

ENGINEER: John Hatch 7 Day Notice Sent: _____
(Please notify Engineer of any major changes prior to work) Do not start operations until: _____
Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 9 5/8" 36.0# J-55 @533' KB Elevation: 4691'
Surface Cmt: 320 sx GL Elevation: 4682'
Long St Csg: 4 1/2" 11.60# J-55 @7310' TD: 7320'
Long St Cmt: 350 sx PBTB: 7215'
Long St Date: 8/31/1984

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7166' - 7176'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" 4.70#, J-55 @ 7148' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____

COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7116', pump 35 sx of cement on top.
- 4) Pull up hole to +/- 2500'. Pump 10 sx balance plug.
- 5) POOH tbg.
- 6) Cut casing @ 584', and LD.
- 7) RIH w/ workstring to 584'. Pump 835 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Clean up location. Reclaim location. RDMOL.