

WORKOVER PROCEDURE

WELL NAME: Wells Ranch AE32-05 DATE: 10/8/2015

LOCATION: Qtr/Qtr: SWNW Section: 32 Township: 6N Range: 62W
Footages: 2011 FNL & 817 FWL

COUNTY: WELD STATE: CO API #: 05-123-30489

ENGINEER: BRIAN ULMER 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# J-55 @ 559' KB Elevation: 4,749
Surface Cmt: 243 sx GL Elevation: 4,733
Long St Csg: 4-1/2" 11.6# M-80 @ 6762' TD: 6,784
Long St Cmt: 550 sx PBTD: 6,714
Long St Date: 5/25/2010

Plug Back (Sand or CIBP):
Perforation Interval (1): Niobrara Perforations: 6,358' - 6,522'
Perforation Interval (2): Codell Perforations: 6,619' - 6,626'
Perforation Interval (3):
Tubing: None Rods:
Pump:
Misc.:

PRODUCTION STATUS: No sustained production since March 2012

COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) Unflange WH and POOH with production tubing.
3) RU WL. RIH w/ CIBP and set @ 6308'. Dump bail 2 sx cement on top.
4) Unland casing. Cut casing off @ 2300'. POOH w/ csg laying down on trailer.
5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
6) POOH w/ workstring to 659'. Pump 208 sx shoe plug. Cement to surface.
7) SI, WOC. RIH. Tag shoe plug. Add cmt if needed.
8) Cut surface casing off 6-8' below ground.
9) Clean up location. Reclaim location. RDMO.