

WORKOVER PROCEDURE

WELL NAME: API 41-15 DATE: 10/8/2015

LOCATION: Qtr/Qtr: NE/NE Section: 15 Township: 4N Range: 66W
Footages: 776' FNL & 678' FEL

COUNTY: WELD STATE: CO API #: 05-123-16562

ENGINEER: AJ Paine 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# J-55 @ 301' KB Elevation: 4,740'
Surface Cmt: 305 sx GL Elevation: 4,728'
Long St Csg: 4-1/2" 11.6#, M-75 @ 7,357' TD: 7,360'
Long St Cmt: 300 & 190 sx PBTD: 7301'
Long St Date: 2/4/1993

Plug Back (Sand or CIBP): Sand
Perforation Interval (1): Niobrara Perforations 6,913' - 7,040'
Perforation Interval (2): Codell Perforations 7,229' - 7,239'
Perforation Interval (3):
Tubing: 2-3/8" 4.7# J-55 @ 7,199' Rods:
Pump:
Misc.:

PRODUCTION STATUS: Currently shut in. Was producing 0.5 bopd and 15 mcf. Pressures currently 591/589
COMMENTS:

- PROCEDURE:
1) MIRU Workover rig, pump & tank.
2) POOH w/ 2 3/8" tbg and lay down.
3) RU WL. RIH w/ CIBP. Set CIBP @ 6,863' dump bail 2 sx of cement on top.
4) RIH w/ workstring to 4,750'. Pump 75 sx balance plug. If maintain circulation, no need to tag plug. (cover Sussex)
5) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
7) POOH w/ workstring to 401'. Pump 155 sx shoe plug. Cement to surface.
8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
9) Cut surface casing off 6'-8' below ground.
10) Clean up location. Reclaim location. RDMO.