

WORKOVER PROCEDURE

WELL NAME: Stromberger 44-12 DATE: 10/9/2015

LOCATION: Qtr/Qtr: SESE Section: 12 Township: 4N Range: 66W

Footages: 520 FSL & 540 FWL

COUNTY: WELD STATE: CO API #: 05-123-16454

ENGINEER: AJ Paine 7 Day Notice Sent: (Please notify Engineer of any major changes prior to work) Do not start operations until: Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8", 24# @ 277' KB Elevation: 4717' Surface Cmt: 195 sx GL Elevation: 4705' Long St Csg: 4 1/2", 11.6#, WC-70 @ 7307' TD: 7308' Long St Cmt: 340 & 180 sx PBTD: 7266' Long St Date: 11/23/1992

Plug Back (Sand or CIBP): Sand Niobrara Perforations: 6854' - 6982' Codell Perforations: 7162' - 7172' Tubing: 2 3/8", 4.7#, J-55 @ 7118' Rods: Pump: Misc.:

PRODUCTION STATUS: Producing 1 bopd and 30 mcf. Pressures @ 300/300 COMMENTS: Can't payout WBI/STEM costs

PROCEDURE:

- 1) MIRU Workover rig, pump & tank. 2) POOH and lay down 2 3/8" tubing. 3) RU WL. RIH w/ CIBP. Set CIBP @ 6804', dump bail 2 sx cement on top. 4) RIH w/ workstring to pump 70 sx balance plug from 4270' - 3360'. 5) Unland casing. Cut 4 1/2" casing @ 2500'. POOH and laydown casing. 6) RIH w/ workstring to pump 100 sx stub plug where casing was pulled. If maintain circulation, no need to tag plug. 7) POOH w/ workstring to 377'. Pump 135 sx shoe plug. Cement to surface. 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed. 9) Cut surface casing off 6'-8' below ground. 10) Clean up location. Reclaim location. RDMO.