

WORKOVER PROCEDURE

WELL NAME: Cecil Farms 06-41x **DATE:** 10/12/2015

LOCATION: Qtr/Qtr: NE/SE Section: 6 Township: 6N Range: 66W

Footages: _____
&

COUNTY: WELD **STATE:** CO **API #:** 05-123-22695

ENGINEER: John Hatch 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @800' KB Elevation: 4878'
Surface Cmt: 560 sx GL Elevation: 4866'
Long St Csg: 4 1/2" 11.60#, M-80 @7516' TD: 7516'
Long St Cmt: 155 sx PBTD: 7500'
Long St Date: 3/2/2005

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 7156' - 7176'
Perforation Interval (2): Codell Perforations 7352' - 7367'
Perforation Interval (3): _____
Tubing: 2 3/8" @7321' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

- PROCEDURE:**
- 1) MIRU Workover rig, pump & tank.
 - 2) POOH w/ 2 3/8" tbg and lay down.
 - 3) RU WL. RIH w/ CIBP. Set CIBP @ 7106', dump bail 2 sx of cement on top.
 - 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
 - 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
 - 6) POOH w/ workstring to 1000'. Pump 343 sx shoe plug. Cement to surface.
 - 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
 - 8) Cut surface casing off 6'-8' below ground.
 - 9) Clean up location. RDMOL