

## WORKOVER PROCEDURE

**WELL NAME:** Noffsinger 44-15 **DATE:** 10/20/2015

**LOCATION:**  
Qtr/Qtr: SE/SE Section: 15 Township: 4N Range: 66W  
Footages: 465 FSL & 670 FEL

**COUNTY:** WELD **STATE:** CO **API #:** 05-123-16529

**ENGINEER:** AJ Paine 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8", 24# @ 300' KB Elevation: 4741'  
Surface Cmt: 240 sx GL Elevation: 4729'  
Long St Csg: 4 1/2", 11.6#, M-75 @ 7325' TD: 7331'  
Long St Cmt: 400+235 sx PBTD: 7290'  
Long St Date: 2/10/1993

Plug Back (Sand or CIBP): **Sand**  
Perforation Interval (1): Niobrara Perforations: 6923' - 7040'  
Perforation Interval (2): Codell Perforations: 7201' - 7217'  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8", 4.7#, J-55 @ 7155' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** Currently SI due to leaking pit.  
**COMMENTS:** Well can't pay out pit repair and remediation work.

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH and lay down 2 3/8" tubing.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6873'. Dump bail 2 sx cement on top.
- 4) RIH w/ workstring to pump 105 sx balance plug from 4900' - 3540'.
- 5) Unland casing. Cut 4 1/2" casing off @ 2500'. POOH and lay down casing.
- 6) RIH w/ workstring to pump 100 sx stub plug where casing was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 450'. Pump 170 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.