

WORKOVER PROCEDURE

WELL NAME: AUFRECHT N02-07 **DATE:** 10/20/2015

LOCATION: Qtr/Qtr: NW/NE Section: 2 Township: 5N Range: 67W

Footages: 932 FNL & 1950 FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-24267

ENGINEER: ENTER YOUR NAME HERE 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8", 24.0# J-55 @ 634' KB Elevation: 4902'
Surface Cmt: 260 sx GL Elevation: 4896'
Long St Csg: 4 1/2" 11.60#, M-80 @ 7562' TD: 7572'
Long St Cmt: 1020 sx PBTD: 7547'
Long St Date: 10/24/2006

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7384' - 7405'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8", 4.70# J-55 @ 7365' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

- PROCEDURE:**
- 1) MIRU Workover rig, pump & tank.
 - 2) POOH w/ 2 3/8" tbg and lay down.
 - 3) RU WL. RIH w/ CIBP. Set CIBP @ 7334', and pump 73 sx of cement on top.
 - 4) Pull up hole to +/- 2500'. Pump 10 sx balance plug.
 - 5) POOH w/ tbg.
 - 6) Unland casing. Cut casing off @ 890'. POOH with casing & LD.
 - 7) RIH w/ workstring to 890'. Pump 300 sx shoe plug. Cement to surface.
 - 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
 - 9) Cut surface casing off 6'-8' below ground.
 - 10) Clean up location. RDMOL.