

WORKOVER PROCEDURE

WELL NAME: AUFRECHT N02-08 **DATE:** 10/21/2015
LOCATION:
Qtr/Qtr: NW/NE Section: 2 Township: 5N Range: 67W
Footages: 917 FNL: & 1951 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-24247

ENGINEER: JOHN HATCH 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8", 24.0# J-55 @ 634' KB Elevation: 4908'
Surface Cmt: 270 sx GL Elevation: 4896'
Long St Csg: 4 1/2", 11.60# M-80 @ 7648' TD: 7660'
Long St Cmt: 970 sx PBTD: 7554'
Long St Date: 10/18/2006

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 7180 - 7194'
Perforation Interval (2): Niobrara Perforations 7298' - 7316'
Perforation Interval (3): Codell Perforations 7479' - 7491'
Tubing: _____ Rods: _____
Pump: _____
Misc.: Stage tool @ 4436' - 4441'

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7130', dump 2 sx of cement on top.
- 4) Pull up hole to +/- 2500'. Pump 10 sx balance plug.
- 5) POOH w/ tbg.
- 6) Unland casing. Cut casing off @ 890'. POOH with casing and LD.
- 7) RIH w/ workstring to 890'. Pump 300 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. RDMOL.