

WORKOVER PROCEDURE

WELL NAME: Dechant X01-02 **DATE:** 10/26/2015

LOCATION: Qtr/Qtr: NW/NE Section: 1 Township: 2N Range: 65W

Footages: 575' FNL & 2103' FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-31914

ENGINEER: Benjamin Daniell 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# J-55 @ 756' KB Elevation: 4841'
Surface Cmt: 274 sx GL Elevation: 4828'
Long St Csg: 4 1/2" 11.6# M-80 @ 7791' TD: 7803'
Long St Cmt: 670 sx PBDT: 7677'
Long St Date: 1/9/2011

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6880' - 6990'
Perforation Interval (2): J Sand Perforations 7565' - 7581'
Perforation Interval (3): _____
Tubing: 2-3/8" 4.7# J-55 @ 7537' Rods: NA
Pump: NA
Misc.: _____

PRODUCTION STATUS: Producing

COMMENTS: Doesn't cover CR49 expansion battery move

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7515', dump bail 2 sx of cement on top.
- 4) RIH w/ CIBP. Set CIBP @ 6830', dump bail 2 sx of cement on top.
- 5) RIH w/ workstring to pump 50 sx balance plug @ 4500'. If maintain circulation, no need to tag plug.
- 6) Unland casing. Cut casing off @ 1950'. POOH with casing laying down on trailer.
- 7) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 8) POOH w/ workstring to 856'. Pump 280 sx shoe plug. Cement to surface.
- 9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 10) Cut surface casing off 6'-8' below ground.
- 11) Clean up location. Reclaim location. RDMO.