

WORKOVER PROCEDURE

WELL NAME:	Fry 13-02		DATE:	11/5/2015	
LOCATION:					
Qtr/Qtr:	SENE	Section:	13	Township:	4N
Footages:	1843 FNL	&	797 FEL	Range:	65W
COUNTY:	WELD	STATE:	CO	API #:	05-123-13303
ENGINEER:	Garrett Reddin		7 Day Notice Sent:		
	(Please notify Engineer of any major changes prior to work)		Do not start operations until:		
			Notice Expires:		
OBJECTIVE:	P&A				
WELL DATA:					
Surface Csg:	8-5/8" 24# @ 311' KB			KB Elevation:	4788'
Surface Cmt:	250 sx			GL Elevation:	4777'
Long St Csg:	4-1/2" 15.1# E @ 7207' KB			TD:	7207' KB
Long St Cmt:	195 sx			PBTD:	7165' KB
Long St Date:	12/31/1986				
Plug Back (Sand or CIBP):					
Perforation Interval (1):	Niobrara Perforations: 6832'-7014' KB				
Perforation Interval (2):	Codell Perforations: 7086-7101' KB				
Perforation Interval (3):					
Tubing:	2-3/8" @ 7060' KB		Rods:		
Pump:					
Misc.:					
PRODUCTION STATUS:	PR				
COMMENTS:					

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6782', dump bail 2 sx of cement on top.
- 6) RIH w/ perf gun. Perforate 4 1/2" casing @ 4545'.
- 7) RIH w/ CICR. Set CICR @ 4445'. Pump 105 sx through and 20 sx on top.
- 6) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 4) POOH w/ workstring to 2500'. Pump 100 sx stub plug.
- 7) POOH w/ workstring to 549'. Pump 215 sx shoe plug. Cement to surface
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.