

WORKOVER PROCEDURE

WELL NAME: Gerrity State G #36-17 **DATE:** 1/4/2016
LOCATION:
 Qtr/Qtr: NWNE Section: 36 Township: 4N Range: 65W
 Footages: 1283 FNL & 1397 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-22820

ENGINEER: Jeanne Van Slambrouck 7 Day Notice Sent: _____
 (Please notify Engineer of any major Do not start operations until: _____
 changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8", 24# @ 620' KB Elevation: 4,841'
 Surface Cmt: 645 sx GL Elevation: 4,829'
 Long St Csg: 4 1/2", 11.60# @ 7,253' TD: 7,253'
 Long St Cmt: 160 sx PBDT: 7,236'
 Long St Date: 6/12/2005

Plug Back (Sand or CIBP): sand
 Perforation Interval (1): Niobrara perforations: 6,820' - 6,902'
 Perforation Interval (2): Codell perforations: 7,102' - 7,116'
 Perforation Interval (3): _____
 Tubing: 2 3/8", 4.7#, J-55 @ 7,063' Rods: _____
 Pump: _____
 Misc.: Notched collar @ 7,075'

PRODUCTION STATUS: 1.3 bopd, 32 mcfd, 395/397 tubing/casing
COMMENTS: In battery with Gerrity State G 36-02, wells cannot pay out relocation costs for CR 49 and STEM

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tubing and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6,770', dump bail 2 sx cement on top
- 4) RIH w/ workstring. Pump 23 sx cement from 4,540' to 4,240' for a balance plug across the Sussex
- 5) Unland 4-1/2" casing. Cut casing off @ 2,500'. POOH w/ casing and lay down.
- 6) RIH w/ workstring to pump 100 sx stub plug where casing was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 720'. Pump 262 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.