

WORKOVER PROCEDURE

WELL NAME: KEISER FEDERAL 13-28 **DATE:** 1/14/2016
LOCATION:
Qtr/Qtr: SW/SW Section: 28 Township: 4N Range: 66W
Footages: 660 FSL: & 660 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-12608

ENGINEER: JOHN HATCH 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @316' KB Elevation: 4768'
Surface Cmt: 220 sx GL Elevation: 4757'
Long St Csg: 4 1/2" 1510# @ 7428' TD: 7432'
Long St Cmt: 230 sx PBDT: 7365'
Long St Date: 7/21/1987

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6966' - 7252'
Perforation Interval (2): Codell Perforations 7266' - 7277'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.70#, J-55 @7240' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6916', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 670'. Pump 225 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. RDMOL.