

WORKOVER PROCEDURE

WELL NAME: MONFORT E30-9 **DATE:** 1/15/2016
LOCATION:
Qtr/Qtr: NE/SE Section: 30 Township: 6N Range: 65W
Footages: 1975 FSL & 720 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-23542

ENGINEER: JOHN HATCH 7 Day Notice Sent: _____
(Please notify Engineer of any major changes prior to work) Do not start operations until: _____
Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24#, J-55 @451' KB Elevation: 4724'
Surface Cmt: 320 sx GL Elevation: 4708'
Long St Csg: 4 1/2" 11.6#, M-80 @7287' TD: 7302'
Long St Cmt: 890 sx PBDT: 7243'
Long St Date: 2/12/2006

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7119' - 7135'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7#, J-55 @ 7105' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7069', pump 35 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2300'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 501'. Pump 175 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. RDMOL.